ABSTRACT

A latch assembly control method and, wherein a latch assembly is integrated with a motor having at least one gear thereof for actuating a plurality of components of the latch assembly. A geartooth sensor can be associated with the latch assembly, wherein the geartooth sensor senses a position of one or more gears, wherein the gear completes less than one revolution to thereby provide a known reference point registration and calibration of the latch assembly via data collected from the geartooth sensor.